

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,968,902 B2
DATED : November 29, 2005
INVENTOR(S) : Stephen P. Fenton et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 18,

Line 44, delete "to" and insert -- to a -- after "tree".

Line 54, after "riser is" insert -- disconnected to position the well drilling derrick assembly above the second wellhead housing. --.

Column 19,


Lines 15 and 44, delete "step".

Column 20,

Lines 33 and 53, delete "land" and insert -- landing --.

Signed and Sealed this

Fourth Day of April, 2006



JON W. DUDAS
Director of the United States Patent and Trademark Office